



HUDSON AVIATION SERVICES, INC., CA

7025 WEST IMPERIAL HIGHWAY
LOS ANGELES, CA 90045-6393
(213) 648-1942

October 10, 1990

Major General Richard Cooke
President
Omstar Products
136 Marine Avenue
Wilmington, CA 90744

Dear General Cooke,

We have recently completed a routine inspection of an engine from a bus of our fleet, This inspection included a complete engine disassembling.

Since we have been using your company's product, D-1280X, for over two years, totaling over 2 million cumulative miles, I thought you would be interested in OUR findings.

I was amazed to see how clean the injectors were, which signifies an excellent firing pattern. The additional lubricity afforded by your product is quite evident in that there was no scoring of upper cylinder walls, valve stems and guides show less than normal wear and the same was true for the upper firing rings.

Carbon build-up is exceptionally low, in fact, where carbon is normally black, we saw only a very low accumulation of what appears to be a gray powdery substance.

All in all, I am again amazed to see what I would consider to be an unusually sub-normal wear pattern in this engine.

In my opinion, the cleaning and lubricating action of D-1280X is a great help in any well run maintenance program.

If you have any questions, please do not hesitate to call.

Sincerely,

A handwritten signature in black ink, appearing to read "Walter Schwarz".

Walter Schwarz
Manager
Maintenance Services